
# **Smoke and Dye Testing Summary**

### **High Level Sewershed**

Run Summary ————————————————————————————————————								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-062	Smoke	9/8/2008	ADS/TM	S15CC1023MH	Dry	Yes	829.20	



## **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Run Summary ————————————————————————————————————								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-062	Smoke	9/8/2008	ADS/TM	S15CC1023MH	Dry	Yes	829.20	

ted Pipes ——			Length	Diameter
Pipe ID	Upstream MH	Downstream MH	(ft)	(In)
S13CC1006G1	S13CC1006MH	S13CC1003MH	133.2191	8
S13CC1003G1	S13CC1003MH	S13CC1025MH	104.8853	10
S13CC1001G1	S13CC1001MH	S13CC1006MH	81.41968	8
S13CC1020G1	S13CC1020MH	S13CC1003MH	96.94914	10
S15CC1012G1	S15CC1012MH	S13CC1006MH	237.4987	8
S15CC1023G1	S15CC1023MH	S15CC1012MH	93.64574	8
S15CC1010G1	S15CC1010MH	S15CC1012MH	81.58628	8

#### **Observations & Photos**

**Obs\_ID** S1028-062-OB01 **Address** 3829 Reisterstown Rd

StatusPrivateSourceCleanoutLocationYard - back

Nearest MH S13CC1006MH

**Comments** Smoke from cleanout in back yard, 10 ft. from

alley. 3829 Reisterstown Rd

**Picture** \S1028-062-OB01-P01.jpg

**Comments** Back of house, 3829

Reisterstown Rd

**Obs\_ID** S1028-062-OB02 **Address** 3831 Reisterstown Rd

**Status** Private **Source** Cleanout

**Location** Yard - back **Nearest MH** S13CC1006MH

**Comments** Smoke from cleanout in back yard, 10 ft. from

alley. 3831 Reisterstown Rd



**Picture** \S1028-062-OB02-P01.jpg

Comments Back of house, 3831

Reisterstown Rd

# **Smoke and Dye Testing Summary**

## **High Level Sewershed**

Nearest MH S13CC1006MH

### **Run Summary**

Kan Sammary									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-062	Smoke	9/8/2008	ADS/TM	S15CC1023MH	Dry	Yes	829.20	_	

Obs\_ID S1028-062-OB03

Address 3833 Reisterstown Rd

Status Private

Source Cleanout

Location Yard - back

**Comments** Smoke from cleanout in back yard, 10 ft from

alley. 3833 Reisterstown Rd



**Picture** \S1028-062-OB03-P01.jpg

**Comments** Back of house, 3833

Reisterstown Rd

**Obs\_ID** S1028-062-OB04 **Address** 3835 Reisterstown Rd

Status Private
Source Cleanout

**Location** Yard - back **Nearest MH** S13CC1006MH

**Comments** Smoke from cleanout in back yard. 3835

Reisterstown Rd



**Picture** \S1028-062-OB04-P01.jpg

**Comments** Back of house, 3835

Reisterstown Rd